

General Environmental Incident Summary

Incident: 4196 **Date/Time Notice:** 8/11/2016 1315 **DEM Incident No:**

Responsible Party: Creek Energy Services LLC

Date Incident: 8/2/2016 **Time Incident:** 1200 **Duration:**

County: Dunn **Twp:** 144 **Rng:** 95 **Sec:** 6 **Qtr:**

Lat: 47.32685 **Long:** -102.75830 **Method:** Interpolation from map

Location Description: Mile marker 102

Submitted By: Mike Hatzenbuhler

Affiliation: Fleet Manager

Address: 4413 Sims ST

City: Dickinson

State: ND

Zip: 58601

Received By:

Contact Person: Mike Hatzenbuhler
4413 Sims St
Dickinson , ND 58601

Distance Nearest Occupied Building:

Release Contained: Yes

Type of Incident: Fire

Description of Released Contaminant: Diesel fuel

Volume Spilled: 15.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: No

Cause of Incident:

Fire to hydrovac truck resulting in diesel fuel leaking from truck, we were able to stop the leak once the fire was put out

Risk Evaluation:

None

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

None

Action Taken or Planned:

Towing company put absorbent material to soak up any fluid that was not burned

Wastes Disposal Location: In process of hiring a company to clean the area

Agencies Involved: Local Fire Department, Local Law Enforcement

Updates

Date: 8/11/2016 ***Status:*** Reviewed - Follow-up Required

Author: Crowder, Kory

Updated Volume:

Notes:

Release of diesel fuel. Follow-up is required.

Date: 8/17/2016 ***Status:*** No Further Action Requested

Author: Souder, Taylor

Updated Volume:

Notes:

Arrived at GPS coordinates and could not locate any diesel staining or smell in ditch area. I recommend closing this site until further notice.